



Boeing BBJ-2 SN32438

Entry Into Service:	February 2002
Time Since New:	9,264.33 Hours
Cycles Since New:	3,403 Cycles

- > 32 Passengers (Private Ops.) / 19 Passengers (Commercial Ops.)
- > Last C-Check (8 Years Check) performed in 2022
- > 1-Year Inspection completed in November 2024
- > 7 Auxiliary Fuel Tanks (2 Fwd and 5 Aft)
- > Last Exterior Paint in 2018
- > Partial Cabin Refurbishment in 2017
- > VIP Lavatory w/ Shower

Boeing

BBJ-2 SN32438

AIRFRAME

Manufacturer / Model	Boeing B737-800 (BBJ-2)
Serial Number	32438
Airframe TSN / CSN	9,264.33 Hours / 3,403

ENGINES

Manufacturer / Model	CFM International CFM56-7B27B3
Engine #1 Serial Number	888210
Engine #1 TSN / CSN	9,264.33 Hours / 3,403
Engine #2 Serial Number	888218
Engine #2 TSN / CSN	9,264.33 Hours / 3,403

APU

Manufacturer / Model	Honeywell 131-9(B)
APU Serial Number	P-5885
APU TSN / CSN	11,091.1 Hours / 7,195

HIGHLIGHTS

32 Passengers (Private Ops.) / 19 Passengers (Commercial Ops.)

Last C-Check (8 Years) performed in 2022

ADS-B Out V2

Specifications are subject to verification upon inspection



Boeing

BBJ-2 SN32438

AVIONICS

Three (3) Collins VHF Transceivers

Two (2) Collins HF Transceivers

Teledyne Communications Management Unit (ACARS)

Cockpit Voice Recorder (CVR)

Fixed ELT

Flight Data Recorder (FDR)

Digital Flight Data Acquisition Unit (DFDAU)

Air Data Loader

Collins Weather Radar

TCAS 7.1

Dual Collins Transponders

Enhanced Ground Proximity Warning Computer (EGPWSC)

Dual Flight Management Computer

Dual Collins ADF Receiver

Dual Collins VOR

Dual Collins DME

Flight Dynamics Head-Up Guidance System

FEATURES

Direct View Camera

LED Lights

MMR

Reinforced Cockpit Door

Specifications are subject to verification upon inspection




Boeing BBJ-2 SN32438

INTERIOR

Configuration:	32 Passengers (Private Ops.) / 19 Passengers (Commercial Ops.)
Crew Rest:	Forward, Two (2) Crew Seats
Galley Location:	Aft G3, G4, G6 Galleys
Lavatory Locations:	Forward, Mid VIP w/ Shower, Aft Guest
Fwd Lounge:	Two (2) 3-Place Divans, Opposite Two (2) Double Divans with Tables, Followed by a Forward-Facing Double Divan
Private Lounge:	Dual 2-Place Divans
Private Bedroom:	Double Bed and Wardrobe
First Class:	Eight (8) First Class Seats
Business Class:	Eight (8) Business Class Seats
Entertainment:	Airshow
Last Refurbishment:	Partial Cabin Refurbishment in 2017

EXTERIOR

Last Paint:	Last Exterior Paint in 2018
--------------------	-----------------------------



Specifications are subject to verification upon inspection



Boeing BBJ-2 SN32438



EXTERIOR

Boeing BBJ-2 SN32438



COCKPIT

Boeing BBJ-2 SN32438



CREW REST

Boeing BBJ-2 SN32438



FWD LOUNGE

Boeing BBJ-2 SN32438



FWD LOUNGE

Boeing BBJ-2 SN32438



FWD LOUNGE

Boeing BBJ-2 SN32438



FWD LOUNGE

Boeing BBJ-2 SN32438



FWD LOUNGE

Boeing BBJ-2 SN32438



HALLWAY

Boeing BBJ-2 SN32438



VIP LAVATORY

Boeing
BBJ-2 SN32438



VIP LAVATORY

Boeing BBJ-2 SN32438



PRIVATE LOUNGE

Boeing BBJ-2 SN32438



HALLWAY

Boeing BBJ-2 SN32438



PRIVATE LOUNGE

Boeing BBJ-2 SN32438



VIP BEDROOM

Boeing BBJ-2 SN32438



VIP BEDROOM

Boeing BBJ-2 SN32438



FIRST CLASS

Boeing BBJ-2 SN32438



FIRST CLASS

Boeing BBJ-2 SN32438



BUSINESS CLASS

Boeing BBJ-2 SN32438



GALLEY

Boeing BBJ-2 SN32438



REFURBISHMENT PROPOSAL - RENDERING

Boeing BBJ-2 SN32438



REFURBISHMENT PROPOSAL - RENDERING

Boeing BBJ-2 SN32438



REFURBISHMENT PROPOSAL - RENDERING

Boeing BBJ-2 SN32438



REFURBISHMENT PROPOSAL - RENDERING

Boeing BBJ-2 SN32438



REFURBISHMENT PROPOSAL - RENDERING

Boeing
BBJ-2 SN32438



REFURBISHMENT PROPOSAL - RENDERING



ÔPUS[^]

aero

Follow @opusaero on



EUROPE | MIDDLE EAST | NORTH AMERICA
www.opusaero.com | info@opusaero.com

